




standard = °

	1 x	→	mm/m
	2 x	→	%
	3 x	→	in/ft (decimal)
	4 x	→	in/ft (fractional)

5

calibration




 +  2 sec.


 → -1- wait ~7 sec.


  

 → -2- wait ~7 sec.

7

 2 sec. → INC

 2 sec. → ABS

6







# QUICK START

## GO! SMART



- 1 On/off switch
- 2 Hold button
- 3 Mode button



## SOLA-Messwerkzeuge GmbH

Unteres Tobel 25, A-6840 Götzis

Tel: +43 (0)5523 53380-0

sola@sola.at, www.sola.at



Please find the operating instructions on  
www.sola.at



SOLA Measures App



R373276

